


# DCX to E-Z-GO-DCS

## FOR SHUNT (SEPERATELY EXCITED) WOUND MOTORS

### (DCX and NCX products)



- NOTES:
- \* FUSES REQUIRED FOR ALL INSTALLATIONS
  - \* DIODE REQUIRED ACROSS COILS / RELAYS
  - \* TDW/RUN SWITCH PREVENTS REGEN WHILE TDWING
  - > ASSUMES FOOTSWITCH IS OPEN WHEN THROTTLE OFF
  - > ALLTRAX RESERVES THE RIGHT TO CHANGE DOCUMENTATION WITHOUT NOTICE
  - > ALLTRAX MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY, OR SUITABILITY OF ANY TECHNICAL OR OTHER INFORMATION PROVIDED
  - > SEE OPERATORS MANUAL FOR MORE INFORMATION

TAB	FUNCTION
1	THROTTLE
2	THROTTLE
3	HORN
4	REVERSE
5	FOOT SWITCH
6	KSI (KEY SWITCH)
7	SOLENOID COIL
8	NOT-USED
9	LOGIC POWER (+)
10	B+ POWER (CAPS)
B+	BATTERY POSITIVE
B-	BATTERY NEGATIVE
M-	MOTOR MINUS
F1	MOTOR FIELD
F2	MOTOR FIELD

REV.	ECO.	DATE	APVD
A	010407	010407	TT
B	013108	103007	RC
C	041708	041708	RC

REV.	ECO.	DATE	APVD
A	010407	010407	TT
B	013108	103007	RC
C	041708	041708	RC

REV.	ECO.	DATE	APVD
A	010407	010407	TT
B	013108	103007	RC
C	041708	041708	RC